

حدود عناصر پایه فولاد خوش تراش

| Element | Low | High |
|---------|--------|-------|
| Al | 0.0005 | 1.40 |
| As | 0.001 | 0.10 |
| B | 0.0001 | 0.025 |
| Bi | 0.0005 | 0.12 |
| C | 0.003 | 1.50 |
| Co | 0.0005 | 1.0 |
| Cr | 0.001 | 5.50 |
| Cu | 0.0005 | 0.80 |
| Mn | 0.001 | 2.20 |
| Mo | 0.0005 | 1.60 |
| Nb | 0.0005 | 1.0 |
| Ni | 0.001 | 5.80 |
| P | 0.0005 | 0.15 |
| Pb | 0.001 | 0.35 |
| S | 0.0005 | 0.50 |
| Sb | 0.001 | 0.10 |
| Se | 0.001 | 0.05 |
| Si | 0.001 | 2.30 |
| Sn | 0.0005 | 0.25 |
| Ta | 0.005 | 0.42 |
| Ti | 0.0005 | 0.50 |
| V | 0.0005 | 1.0 |
| W | 0.001 | 2.20 |
| Zn | 0.0002 | 0.035 |
| Zr | 0.001 | 0.40 |